

Connector Board

Page 01 : Index
Page 02 : Top
Page 03 : Headboard Interface
Page 04 : HSM Connector

Revision Notes

Data	Revision	Page	Content
2009.09.23	REV 0.1		Draft Version
2009.10.30	REV 0.2	3	Change Boom
2009.11.11	REV 0.3	3	Add 0 ohm resistors at U4 U5
2009.11.13	REV 0.4	4	Pin Swap





